


Flat Steel Mount Installation and Information Guide

Included with your ROCKFLEET



Fitting Instructions

- 1 Fit your ROCKFLEET to the flat steel (deck) mount using the stainless machine screws & washers provided within the box
- 2 Make sure the white plastic washers go between the ROCKFLEET and the flat steel (deck) mount!
- 3 Run the power cable attached to the ROCKFLEET to your vessels power supply. Make sure you check the length before installation
- 4 Secure the flat steel (deck) mount to your vessels deck (no screws provided)

Maximum screw torque limit - 6 N.m

Maximum Bend Radius



6 x outer diameter

Temperature Range



-40°C to +80°C

Red & Black Cable Cores



Red Core = +ve

Black Core = -ve

Power Supply Required



Attach the cable to a fused (2A) 8-32v DC supply

For further enquiries on how to install your RockFLEET, please contact us:
0800 SAT COM | info@pivotel.co.nz